

INVESTIGATIVE REPORT

Case No. <del>XXXXXXXXXX</del>				
TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: \_\_\_\_\_

DATE &amp; TIME OCCURED: \_\_\_\_\_

VICTIM: \_\_\_\_\_

ADDRESS: \_\_\_\_\_

PHONE NUMBER: \_\_\_\_\_

NARRATIVE: was dressed in a pair on sneakers, short pants and shirt.  
After speaking with Deputy Cavender, I drove to the location  
of the incident where I observed the residence, It being a small  
white frame hose having a front and rear concrete porch area, furthe  
r having an add on onning type car port to the west side of the resi  
dence, further having a small wooden storage shed located directly  
to the rear of the back porch of the residence being approximatly  
15 feet from the porch, further the before mentioned dog pen was  
located to the rear of the shed attatched to the rear of the shed.  
The pen was made of wooden post placed approximately 8 to 9 feet apart  
having what appeared to be 36 inch by 4X4 farming fence attatched  
on the outer side of the post and to the rear of the shed. The meas  
urements of the pen where approximately 36 foot deep and 42 feet in  
width, measurements where stepped off being 12 steps by 14 steps.  
I furter examined the described pen and was unable to locate the  
electric wiring as described by Sgt Hilliard in his report or by  
Deputy Cavender whom I had previously talked with. I further observe  
d two chow dogs that occupy the pen. Afterwards I walked to a neigh  
bors residence located due west of the residence, there I spoke with  
a White male and female who told me that they where at home when the  
incident occured but that they where mowing the yard and did not know  
that anything had occured until the emergency vehicles had began to

STATUS: ACTIVE ☐  
 PENDING ☐  
 INACTIVE ☐  
 CLOSED ☐

CRIMINAL INVESTIGATOR  
 ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/78

INVESTIGATIVE REPORT

Case No. <del>88-00000000</del>				
TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: \_\_\_\_\_

DATE &amp; TIME OCCURED: \_\_\_\_\_

VICTIM: \_\_\_\_\_

ADDRESS: \_\_\_\_\_

PHONE NUMBER: \_\_\_\_\_

NARRATIVE: arrive at the residence. They further told me that the entire family was at the funeral home at the time of my visit and further that since the incident that ~~Mr. [redacted]~~ had taken the electric fence down. Afterwards I went back to the residence where I obtained my camera and photographed the residence, shed and dog pen described earlier. Further a Mr. ~~[redacted]~~, app 18 Y.O.A. arrived at the residence and was obviously grief stricken by the death of his younger brother, he took me to the rear of the residence and took out a control box that operated the electric fence and gave it to me and further told me that I was welcome to look around the residence if I wished, further that he was not at the residence the day of the incident but that his uncle ( ~~Mr. [redacted]~~ ) was also very upset as to what had happened. Afterwards I took the control Box to my unit where I examined it closely and further photographed it. and afterwards listed all pertinent information as follows:

Produced by: FIDO-SHOCK inc. 5360 National Drive, Knoxville Tenn, 37914. "Solid State Pet Deterent electric fence controller". Power by 110-120 Volt, 60 Hz Ac. "DANGER" Any Alterations to the designe of this charger may cause seriouse electrical shock. Further showes an intermittent output of current and showes to be used with 12 to 20 quage wire only. Model # SS-750. also below is a square silver sticker with B-6 labeled on it. The device is U/L listed No. 11N0. Serial

STATUS: ACTIVE ☐  
 PENDING ☐  
 INACTIVE ☐  
 CLOSED ☐

CRIMINAL INVESTIGATOR  
 ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

280

Page 2 of 6

INVESTIGATIVE REPORT

Case                     

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: \_\_\_\_\_

DATE & TIME OCCURED: \_\_\_\_\_

VICTIM: \_\_\_\_\_

ADDRESS: \_\_\_\_\_

PHONE NUMBER: \_\_\_\_\_

NARRATIVE: No. G-04346. also a code No. 305-159 in the lower left corner. Also in the lower center of the device is a label listed "Use 1/16 Amp time delay fuse only" I further upon examining the two fuses contained in the device found them to be 1/4 Amp, 250 Volt No. 313 each both showing manufacturer code as L F Fuse. Both fuses being four times the strength recommended by the manufacturer.

After leaving the  residence, I returned to my office where I called the Vanderbilt Emergency room to find out what the results of the autopsy that I understood that they had performed. I was told by a nurse there that they did not perform an autopsy that the body was sent to the metro medical examiners office. Afterwards I contacted the medical examiners office where I spoke with Doctor Simpkins. He further told me that he did not perform an autopsy that the body was brought to there office simply for record purposes only. He further told me that the probable cause for death was cardiac arrest due to an electrical shock. he further told me that the victim had a small burn on the left posterior wrist, also to the rear of the right knee joint. Doctor Simpkins further told me that he did not examine the victim that he recieved his information from the Vanderbilt Emergency room report and he further was unable to tell me the Doctor name who examined the victim.

STATUS: ACTIVE ☐  
PENDING ☐  
INACTIVE ☐  
CLOSED ☐

                      
CRIMINAL INVESTIGATOR  
ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

281

INVESTIGATIVE REPORT

Case No. <del>                    </del>				
TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: \_\_\_\_\_

DATE &amp; TIME OCCURED: \_\_\_\_\_

VICTIM: \_\_\_\_\_

ADDRESS: \_\_\_\_\_

PHONE NUMBER: \_\_\_\_\_

NARRATIVE: Afeterwards I obtained the name and phone number of the Doctor who was a Dr. . Phone No. . I called Mr.  and after he verified my position I asked him pertinent questions about the victim. He told me that the child was brought into the emergency room in full cardiac arrest and that hte family told him that the child had been shocked by an electric fence. He further told me that the family was obviously grief stricken and that he did not suspect any foul play. He further told me that he could not offer any information as to the crime scen itself but that there was a burn mark on the leg of the victim and that it appeared that it could have been caused by an electrical fence. I further ask the Doctor if a small amperage such as the before mentioned control box could have caused the childs heart from beating, he then told me that he was not familiar with electricity and that it was the first case of this nature that he had seen but that all he knows is that an electrical shock can and on some occasions will stop the heart from beating. I was unable to obtain any further information from Dr. . After speaking with him I prepared an authorization for medical information release form in wich I plan to have a family member signe and obtain all medical records pertaining to this case.

STATUS: ACTIVE ☐  
 PENDING ☐  
 INACTIVE ☐  
 CLOSED ☐

                      
 CRIMINAL INVESTIGATOR  
 ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/14/78

88 A0117

NASHVILLE, TN.....  
NASHVILLE.....  
7/19/88

15

## 21 Greenbrier 4-year-old dies after shock from fence

From Banner staff reports

**GREENBRIER** — A 4-year-old Greenbrier boy died Saturday around 7:30 p.m. after he apparently stumbled into an electric fence and was severely shocked, according to Robertson County Sheriff's deputy Charles Hillard.

The child, ~~Shannon~~ and his sister were visiting the home of ~~Walter~~ in Greenbrier about 21 miles north of Nashville.

~~Shannon~~ told police the boy was playing with some other children about 5:30 p.m. Saturday in the backyard when he

stumbled into an electric fence inside a dog pen.

The 24-volt electric fence is used, ~~Shannon~~ said, to keep the dogs away from the fence surrounding the pen.

The child, the son of ~~Shannon~~ and ~~Shannon~~ of ~~Memphis~~, was taken by the Lifeflight helicopter to Vanderbilt University Medical Center, where he later died.

While on their way to the scene, Robertson County Emergency Medical Service workers notified Vanderbilt about the situation.

The emergency helicopter flew to the scene and landed in the neighborhood, according to

Robertson County Emergency Service Director Bob Fletcher.

"The sheriff's deputy was already on the scene so they started CPR," Fletcher said.

~~Shannon~~'s body has been taken to Nashville General Hospital to be examined, Vanderbilt officials said today.

Robertson County Chief Deputy Milton Frederick said the department is still investigating the incident.

"We'll probably have a comprehensive report later today," Frederick said.

Frederick said officials are investigating to see if the fence was operating properly when the child fell on it.

Epo.5

OCT 31 1988

8811150002060

ATTACHMENT 5 283

11.15.88 02:21 PM P03

11. 15. 88

2:28 PM

# ACCIDENT INVESTIGATION REQUEST FORM

Document Number 28A0117A1 Category I.D. SECTIS  
Date of Incident 9/17/88 Hazard Analysis ☐  
Follow-up Requested Telephone Call ☐  
Type Follow-up Requested 492-6608  
Headquarters Contact Dave Johnson  
Assignment Message Conduct an investigation of  
electrical fence related death reported  
the attached news article. Contact  
officials for information on the  
the accident scene and the  
(malfunction of unit). Obtain a  
any report regarding this death.  
that of any analysis of the product

Person(s) to Contact Co. Sheriff Det. Chase  
Robertson Co. Sheriff  
Milton Frazier

December, 1988

Guideline

Requested By Decker  
Task Number 881115000-2060 Date 11/15/88  
Assigned to Choi

204

2/5/91

Form 2 PD Input

USE THIS FORM WITH A "go" PD ONLY IF FILE ALREADY IN COMPUTER

All dates are yymmdd

FILE NO: R P890087 LOGBOOK NO: L B900099 DATE OF P.D.: 90 04 25

HAZARD PRIORITY B COMPLIANCE OFFICER: TIM JONES

NEISS CODE: 0605 TYPE CAP: VOLUNTARY MANDATORY

HOW DISCOVERED: FIRM REPORTED ON 4/17/89

FOLLOWING RECEIPT AND REVIEW OF  
881115CCC 2060.

COMPANY NAME FI-SHOCK INC.

TOTAL INVOLVED: 13,966 TOTAL CORRECTED 0 RETAIL PRICE 0.00

SAMPLE #'s: \_\_\_\_\_

DATES PRODUCED: 850719 THRU: 900417 DATES DIST 850719 THRU: 900417

NATURE OF HAZARD: ELECTRIC SHOCK OR ELECTROCUTION

INJURIES: 1 FATALITY REPORTED

GEOGRAPHIC DISTRIBUTION: NATIONWIDE X REGIONAL   

CORRECTIVE ACTION: NONE

NG CHNG    QC CHNG    DISCON PROD    REFUND    REPLACE    REPAIR    OTHER X

KEYWORDS SHOCK

Keywords help you locate categories of files by product, injury, or other category

285

PDEF-INPUT-#2:

NOTIFICATION COMMENTS:

NONE

PRESS RLSE- DIST LTR RET LTR CONS LTR SIGN POSTED  
PAID RADIO- PAID PRINT PAID TV TEL CALL OTHER ☒

COMMENTS:

FILE CLOSED FOLLOWING A REVIEW  
OF CPSC DATA BASE INFO, INVOLVING ELECTRIC  
FENCES AND CONTROLLERS, AND REVIEW OF ID 76-133.

2nd FIRM:

STREET:

CITY:

STATE: ZIP:

REP:

PHONE:

(the fields below update your original entry)

PRODUCT DESCRIPTION:

BRAND:

MODEL:

CPSC ACTION:

FORM 1A  
Initial input and staff worksheet

4/24/89  
RECEIVED BY: Jeri Rogers  
TIME: 10:15  
HAZARD PRIORITY: \_\_\_\_\_

CORRECTIVE ACTIONS DIVISION  
REPORT SHEET: OFFICE USE ONLY

NUMBER: RP 890082 DATE OPENED 890417 (yyymmdd) DT CLOSED 901025

CACA CONTACT: T. JONES RO: FOCR

COMPANY NAME: Fi-Shock, Inc.

ADDRESS: 5300 National Drive

CITY: Knoxville STATE: TN ZIP: 37914

COMPANY CONTACT: DAN McCARTER TELEPHONE: 615-524-7380 Outside  
Counsel \_\_\_\_\_

TYPE: MFG ☒ DIST \_\_\_\_\_ RETAIL \_\_\_\_\_ PVT LBLR \_\_\_\_\_ IMPORTER \_\_\_\_\_

NEIS CODE: 0605 TOTAL INVOLVED 10000

PRODUCT DESCRIPTION pet deterrent

MODEL: ~~890082~~ # SS-750

CEO/Delegate if different  
from above:

BRAND: FIDO-SHOCK

POT. HAZARD: electric shock

COMMENTS: ID188115CCC2060

REPORTEDLY INVOLVES THE ELECTROCUTION OF A FOUR YEAR OLD BOY.  
(END COMPUTER ENTRY)

II. ADDITIONAL PRODUCT IDENTIFICATION

A. Identification/Serial Number:

B. Location of Serial/Model Numbers:

C. Certification on Product (UL, etc.):

D. Average Lifetime of Product:

E. Unit Retail Value:

*Unit is UL listed  
Listing Report  
available*

III. ADDITIONAL DEFECT AND HAZARD INFORMATION

A. Description of defect: unk

PSA 5400

TJ 7/5/80

101a

1) 801118CEP0102

Acc date - 10/30/79

- Cow reportedly electrocuted from malfunctioning electric fence controller. - No evidence of defective fence controller or that cow was electrocuted

- Mpi. Agway, De Witt, NY.

2) 881115CCC 2060

Fi-shock-dre, incident of which led to RP 89-87

3) 800811DA5054

Acc. Date - 7/30/80

- 29 yr. old goat shocked from livestock fence controller, stunned him, but no other problems reported.

- Sears Model 436-22032 Fence Controller

4) 790919CEP0849

Acc date - 8/11/79

288

- 22 yr. old male received severe elec. shock when he contacted electrified fence from controller; reportedly was unconscious but recovered. (Fence was not used then.)

Death Certificate (1973-1980)

1) 648032463

Date of Acc. - 4/21/76

9 yr. old boy electrocuted when he fell  
across an electric fence while playing  
- Brand not identified

2) 848073271

Date of Acc. - 8/8/78

1 yr. old boy electrocuted when he  
~~fell across~~ was shocked by a  
faulty electric fence while playing  
- Brand not identified

3)

YSA 5400

7/5/80 T.J. ~~6/1/77~~

Incidents (1971 1973 to 1990)

---

1) H 03016A0-81 (801118 CFP 0102)  
10/79 ~~shock incident~~

Electric Fence Centrols Shock Pulse Comes  
Very Fast

Azway (band)

(Same as 10/7)

FOR OFFICIAL USE ONLY

PROPRIETARY

ATTACHMENTS:

YES NO  
YES NO  
YES NO  
YES NO

PRODUCT SAFETY ASSESSMENT (PSA) TECHNICAL EVALUATION REQUEST  
Note: Print, use black pen, no blue ink.

Requested by: TH JONES Org. Codes: CACA

FO CH

Date: 6/14/90 Priority: B

Case#

RP 89-87

PRODUCT INFORMATION

Manufacturer: EI-SHOCK, INC. State: TX

Product: ELECTRIC FENCE CONTROLLER

Brand name, model, etc. EI 100-SHOCK, MODEL NO. SS-750

Sample number: \_\_\_\_\_

Sample Disposition: RETURN TO CO 1-1 STORE AT UNSE

EVALUATION REQUESTED:

DATA BASE INFORMATION RE.

ELECTRIC FENCES AND ELECTRIC FENCES

CONTROLLERS CONCERNING A ELECTRIC SHOCK AND

ELECTROCUSSION INCIDENTS. (NEISS COPIES

INCULC 1001, 1871, 0605.)

EP ASSESSMENT: DATES: FROM 1973 TO 6/90 SORT BY MFG. YES X NO

X 101 X 111 NEISS COMMENTS NEISS ESTIMATES X 0TH MFIRS

Hazard: ELECTRIC SHOCK/ELECTROCUSSION

PSA ACTION (FOR PSA USE ONLY)

Request number: 5400

Compliance no.: RP 89-87

Priority: B

Received: 6/18/90-7:00 A  
(time/date)

Date Requested: 6/21/90

Due Date: \_\_\_\_\_

Mfg. EI-SHOCK INC.

Product: Electric Fence Controller

Req'd. by: JONES Org. CACA

ASSIGNMENT:

Date: 6/18 Org: EP

Assigned to: Edwards

Req. Summary: Data Review

Electric Fences &

Controllers

Completed: \_\_\_\_\_

DIRECTORATE FOR EPIDEMIOLOGY

DATA REVIEW

TO : Jim Jones *sent for FB*  
 FROM : EPI/EPHA *70-210144*  
 REQUEST: #5400 Fido Electric Fence Controller  
 DATE: 6/29/90  
 DATE DUE: 6/21/90  
 PRIORITY:

HAZARD PATTERN: Electric Shock, Electrocution

SELECTION CRITERIA:

Product Code(s): 0605, 1001, 1871, 4063  
 Text/Other : Fido, Control  
 Time Frame : January 1, 1973 - June 29, 1979  
 NFIRS Search Criteria:

INCIDENTS IDENTIFIED:

Data Base(s)*	# of Incidents	# of Deaths
Accident Investigations	<u>1</u>	<u>1</u>
Reported Incidents	<u>1</u>	<u>1</u>
Death Certificate File	<u>1</u>	<u>1</u>
NEISS (Actual number)	<u>1</u>	<u>1</u>
NFIRS	<u>1</u>	<u>1</u>
TOTAL	<u>5</u>	<u>5</u>

\* Incidents reported in more than one data base are included only once, in the data base listed first. These are reports EPHA was able to identify from the CPSC data files and should not be considered a statistical sample or a complete count of all such incidents that may have occurred.

NOTES/COMMENTS:

DIRECTORATE FOR EPIDEMIOLOGY

DATA REVIEW

TO : Jim Jones  
 FROM : EPI/EPHA 50-Quint St  
 REQUEST: #5400 Fido Electric Fence Controller

DATE: 6/29/98  
 DATE DUE: 6/21/98  
 PRIORITY:

HAZARD PATTERN: Electric Shock, Electrocution

SELECTION CRITERIA:

Product Code(s): 0605, 1001, 1871, 4063  
 Text/Other : Fido, Controller  
 Time Frame : January 1, 1973 - June 20, 1979  
 NFIRS Search Criteria:

INCIDENTS IDENTIFIED:

Data Base(s)*	# of Incidents	# of Deaths
Accident Investigations	<u>1</u>	<u>1</u>
Reported Incidents	<u>—</u>	<u>—</u>
Death Certificate File	<u>—</u>	<u>—</u>
NEISS (Actual number)	<u>—</u>	<u>—</u>
NFIRS	<u>—</u>	<u>—</u>
TOTAL	<u>1</u>	<u>1</u>

\* Incidents reported in more than one data base are included only once, in the data base listed first. These are reports EPHA was able to identify from the CPSC data files and should not be considered a statistical sample or a complete count of all such incidents that may have occurred.

NOTES/COMMENTS: